

Work Inspection Camera RICOH SC-20

Easy Setup MANUAL

RICOH INDUSTRIAL SOLUTIONS INC.

Setup procedure

Explanation	Image
proroquisite	
prerequisite	HDMI monitor
Please prepare some tools yourself.	
Required environment for handling the SC-20	HDMI cable
Monitor/HDMI® cable	
 USB Mouse/USB Keyboard 	100 to 240 V AC AC cord USB Type-C USB hub
	50/60 Hz
Option	
 USB flash drive/SD card 	AC auapter
 USB hub (3 or more ports) 	
	Lens USB mouse
	USD Reyboard
process 1 : Power on	
Press the power button.	Power button
	rower buttom
	0
process 2 : Initial Setting	Initial Settings
The initial setup screen will be displayed at first startup.	Regional Settings
For use in Japan, please configure as follows.	Area Asia -
Example	Location Tokyo -
Regional Settings	Language Japanese -
Area Asia	Keyboard jp106 -
	Use software keyboard for input
	Initial Password Settings
Language Japanese	User ID : Administrator
Keyboard : jp106	Password * :
	Retype Password * .
Click the Save and Reboot the system.	O Save
The settings can be changed at any time from the "Initial	
Settings" menu under "System Settings".	
process 3 : Log in	
Log in as an administrator. Enter user ID "Administrator"	RICOH
and click the	
Login button.	
	Login
process 4 : Setting sensor control	Sensor Control Display Control Display
Cital Sensori	Exposure Exposure
Click Display button on upper right corner of the	Auto Set Default Auto Set Default Target Point Target Point
screen.	○ Manual ○ Manual
From the Sensor Control menu, display the camera image	Gain Gain 31
settings screen.	Shutter Speed 29.641 29.641 29.641
 Adjust the exposure compensation (brightness), using 	White Balance White Balance
the slide bar under [Target Point]	Manual Manual
Check [Manual] to make detailed settings for gain	Gain R Gain R Gain R
shutter speed and white balance	Gain B 2454 C Gain B 2454 C
shatter speed, and write buildice.	Gamma Gamma
* Adjust the color and chang to the most visible state	Set Default Curve Value Curve Value
Aujust the color and shape to the most visible state	
while viewing the image of the target object.	OFF Set Default OFF Set Default
	Auto Manual

<pre>process 5 : Focus adjustment Turn the focus ring on the lens and adjust the focus so that the image of the object is clearly displayed. *The focus can be adjusted even more precisely by using [Scale] in the [Display] menu to display the image in equal size.</pre>	Sensor Control Display Auxiliary Line Scale 100% Fit Fit Focus Ald (Show Edge)
process 6 : Capturing the Master Image	
This function allows you to canture a master image. Place	2026/11/21 18:06:31
the object in the completed state (i.e., the work has been	Capture Sensor/
done correctly) and click	Dispay
	Anchor Point
button in the upper right corner of the	
	Example: Parts insertion \rightarrow Cover installation \rightarrow Screw installation
Set the destination and file name and save the image.	If the above three processes are involved, three master images are required.
*This is to prepare an image of the completed state (what it	
should be) of the process to be judged by the camera. The	
camera compares this image with the state of the work in	
progress, and judgment is made as to whether or not they	
match.	
*In the case of assembly work, a master image for each work	
item (Item_1, 2,) is required.	
A series of workflows are registered as a [lob ID]	Job ID Settings
Multiple work processes from the start of inspection to	Alias Settings
the end of inspection are defined in a single []ob ID] for	Other Settings
the object to be assembled by the operator	Job ID List Instruction Steps
the object to be assembled by the operator.	Default Add Work_1
Click [Job Settings] - [Job ID Settings] at the top of the	Delete
screen to display the settings screen. at the top of the	
screen to display the settings screen.	Enter Job ID Name
Click the [Add] button in the Job ID list to register a new	Exposure Gamma Instruction Step File ID-1
Job ID.	Gain Curve Value 3 2 Gancel OK
	29.641
	White Balance Filter
process 8 : Setting the "Instruction Steps"	Job ID Settings
In the [Job ID List] on the left side of the screen, select	Job ID List Instruction Steps Inspect
the Job ID registered in step 7.	ID_11 Copy Copy Delete
Work_1" is automatically created in [Inspection Steps] in	L'elere Delere
the center of the screen. Example: If there are the three	
processes: Parts Insertion \rightarrow Cover Installation \rightarrow Screw	Enable Mod Infinite Loop Mode
Installation,	
	Production volume management

Work_2 for cover installation, and Work_3 for screw installation.

Create as many work items in the Inspection Steps as the number of required processes by clicking the "Add" button.

*If there are work instruction images, select the work instruction image from the Instruction Step File [...] under [Instruction Steps] in the center of the screen. The work instruction image will be displayed in the lower area.

*Only JPEG images can be used for the Instruction Step File. Please convert data created in Word, PowerPoint, Excel, etc.

to JPEG using the provided editor software.

uto	Curve Value	
	2	St
		Li

process 9 : Setting the "Inspection Steps"	Instantion State				
"Item_1" is automatically created in [Inspection Steps]	Item_1 Add				
on the right side of the screen. Up to 20 points can be	Copy Delete				
determined for one work item.					
If you need to judge more than 21 points, please add					
the item.	Mode Matching ~				
process 1 0 : Select Master Image					
Press the [] button to select the master image	Inspection Steps				
captured in process 6.	Add Copy				
The master image is displayed in the master image	Delete				
display area.					
	Mode Matching *				
	Master Image				
	/userdata/work/master_20231120.png				
	Disable Standard (sec) 30				
	Limited (sec) 60 -				
	Save Image				
process 1 1 : Set checkpoint	Moster Settings				
Click on the master image in Process 10 to set the	Master Settings				
checkpoints.	Show All Anchor Point ROI Check Point				
Checkpoints \rightarrow Specify the actual work area.					
Up to 20 checkpoints can be set.	When a checkpoint is specified, a yellow dotted frame is displayed. The number of the search order is displayed in the				
*To set more than 21 checkpoints, add items from the "Add"	frame.				
button in Process 10 [Inspection Steps] and set the 21st and	• The maximum specified size of checkpoint is 500 (pixel) x 500 (pixel).				
subsequent checkpoints.	• The minimum specified size of checkpoint is 50 (pixel) x 50 (pixel).				
*Anchor point is set to specify the location of the object. The					
position of each checkpoint is specified by the relative distance					
from the Anchor point, and judgment is made.					
*The maximum and minimum ranges of checkpoints are					
determined.					
process 1 2 : Checkpoint Parameter Settings					
F	Check Point Parameters				
Right-click on the checkpoint (yellow frame) set in	Matching Order				
Process 11 and select	Check Method Shape -				
"Parameter Settings" to configure detailed settings.	Similarity 0.75 C				
[Similarity Inversion] \rightarrow Threshold can be set. The	Rotation Angle				
score is 1.00 for a 100% match.	Search Area				
Ideally, the similarity should be	3.0 v				
adjusted by checking each score					
before and after the work to be	*The rotation angle values are +9 (+109 in the example at left)				
inspected.					
[Rotation Angle] \rightarrow Sets a tolerance range from 1 to					
180 for any variation in the rotation of					
the checkpoints.					

[Search Area] \rightarrow Sets the size of the checkpoint sea area.	n
Example: If the checkpoint is 100	x
100 pixels and this setting is 1	<i>5,</i>
the image on the right is shown	

Tips Work Inspection Flow

- Q: What is the work inspection process for SC-20?
- A: For each checkpoint, the degree of conformity of the shape (or color in the case of color recognition) with the master image is measured by image recognition, and if they match, it is judged as OK. The setup work can be repeated to find the optimal settings while repeatedly testing the judgment, thereby preventing misjudgment.

Checkpoint	Actual inspection points. For example, in the case of screw tightening work, the screw point is the checkpoint.					
Test	Function to test the judgment. Click the thumbnail image of the checkpoint on the right side of the standby screen and click the "Test" button in the dialog to test.					
Score	This is a numerical value of the shape matching (or color matching in the case of color recognition) with the master image. A score of 1.00 is assigned when there is a 100% match with the master image.					

Glossary

Tips Logic for Judgment

- Q: What logic is used to calculate scores for "shape" and "color" recognition, respectively?
- A: In the "Shape" check method, the image to be inspected is binarized, and the degree of agreement is calculated by comparing only the shape of the outline (color differences have no effect). The "Color" check method compares the area of the color specified in the "Specified Area" to calculate the degree of matching (shape differences have no effect).

Shape	Color
Similarity: Outline similarity (Any color)	Similarity: Designated color area similarity (Any shape)
Application: For shape differences	Application: For color differences For designated color area differences
Subject of inspection Score	Subject of inspection Score
Master image / Sample 0 0.997	Master image / Sample 0 0.993
Sample 1	Sample 1



Sample 2



Usage example: Check for screws







Tips Checkpoint size

Q: How large should the checkpoint be?

A: When specifying checkpoint, the size of the area to be surrounded is important. Perform a "test" of the judgment before and after the work to be inspected, respectively, and set the size to which the score difference is the largest.

This is the trick !

Trick①	 Basically, set the minimum size according to the size (shape) of the object to be inspected. If other items are included, the score will also reflect the size of the items, and therefore, the difference in score tends to be less pronounced.
Trick ②	If the score varies with the minimum size and the judgment is not stable, please try a slightly larger enclosure. Since SC-20 is a high-definition product, the scores may be skewed depending on the way the light hits the object or the condition of the object. In such cases, including the area around the object to be inspected in the checkpoints will stabilize the score difference and make it effective.
Trick3	 If the inspected object is too large to fit in the specified size of checkpoint, please specify a characteristic point of the inspected object (a point where there is a clear difference between before and after work). The maximum specified size of checkpoints is 500 (pixel) x 500 (pixel). The minimum checkpoint size is 50 (pixel) x 50 (pixel).

Q: Do I need to set parameters for checkpoint?

A: The accuracy and speed of judgment can be improved by adjusting the parameters of each checkpoint. There are three parameters to adjust: "Similarity," "Rotation Angle," and "Search Range".

Similarit	ity Set how much the score (shape matching with master image (color matching in case of color recognition)) is acceptable for judgment, and the lower limit for OK.							
Rotation	Angle Set the rotation screw	igle Set the acceptable range for judgment when the inspection target is rotating, from $\pm 1^{\circ}$ to $\pm 180^{\circ}$. This parameter is especially important for screw tightening work.						
Search R	ange Set the equiva wider	e width of the search ra lent checkpoint width i the search range.	ange when locating the s set to 1.0, and the	e inspection target. The larger the number, the				
This	s is the trick !							
Trick①	The best value for "Sin	nilarity" is based on the	e results of the test.					
	For example, if the test	results are [Before: 0.3	7] and [After: 0.98], se	et any value in between.				
	The closer the set value	e is to the pre-work valu	ue, the more lenient th	e judgment will be, and				
	the closer it is to the post-work value, the more severe the judgment will be.							
Trick ^②	The "Rotation angle" value should be set to [45] (±45°) for screw tightening operations,							
	since there are variations in the rotation state of screws after the operation.							
Trick3	If the value of "Search	Range" is set too small,	, it may not be possible	to locate the inspection				
	target, so first test with the default value [3.0]. If there are objects of similar shape near the							
	object to be inspected, adjust the value smaller if necessary.							
	For three-dimensional objects such as screws, set the value to [1.2] or higher.							
Trick ⁽⁴⁾	If there are different	-colored items, two ch	neckpoints can be set t	for the same inspectior				
	target, and the check	method can be set t	o "shape" and "color	" matching to prevent				
	misjudgment.							
	Check Point Parameters	Check Point Parameters						
	Check Method Shape •	Similarly 0.75						
	Rotation Angle	Color flotting Master Imago Select Area						
	Search Area	Toterance 15 ; C						
	Cancel	Cancel						
nt ROI			Master Settings					
	E Show All	Anchor Point	Anchor Point ROL	Check Point				

_	
Inccar(/
1055ar v	/

Process	13	:	Anch	or P	oint//	Anch	or	Poir	٦t	ROI
settings										
After the	chor	-1	aainta	have	haan	ect	ect	the	۸	char

After the checkpoints have been set, set the Anchor Point.

*If you are using a positioning mechanism (e.g., a jig to place

an object (product) in a fixed location) for assembly, you do not need to set reference points.

- Anchor Point \rightarrow Set a point that serves as a

When [Anchor Point] is specified, a green frame is displayed.

٠

The maximum specified size of the Anchor Point is 700 (pixel)x700 (pixel).



positioning reference for the object. Specify the
 area where there is a feature and no similar A
 shape exists.

• Anchor Point ROI \rightarrow Set the area where the Anchor Point is searched.

*The Anchor Point is set to specify the location of the object. The position of each checkpoint is specified by the relative distance from the Anchor Point, and judgment is made.

*The maximum and minimum range of the Anchor Point is determined.

The minimum specified size of the Anchor Point is 50 (pixel)x50 (pixel).

A light blue dotted frame is displayed when specifying the area for [Anchor



Q: Why is it necessary to set an Anchor Point

A: To specify the location of the object (product) to be assembled and one anchor point from which to search for checkpoints.
 Since the setting of the anchor point affects the speed at which the inspection starts and the accuracy of the judgment, we recommend making optimal adjustments here as well.

*When using a positioning mechanism for the object (product) to be assembled (e.g., a jig to place the product in a fixed location), setting of an anchor point is not required.

This is the trick !

Trick ①	Specifying a position as close as possible to each checkpoint reduces errors in relative position to the checkpoint and improves search accuracy.
Trick ^②	As with checkpoint, the Anchor Point is searched for by comparison with the master image through image recognition. Therefore, specify areas where the shape is unique and no similar shape exists.
	 The maximum specified size of an Anchor Point is 700 (pixel)x700 (pixel). The minimum specified size for an Anchor Point is 50 (pixel)x50 (pixel).
Trick3	Please specify a part of a shape that includes straight lines, not a circular object. If you specify a circular object, the orientation of the object's installation will be incorrectly recognized, resulting in a large error in the relative position to the checkpoint.

Tips Anchor Point ROI

Q: What is the Anchor Point ROI?

A: In order to search for the Anchor Point quickly and improve processing speed, the search can be focused on the area specified in the "Anchor Point ROI" instead of the entire screen.

*If you do not set an Anchor Point, you do not need to set a search area.

■■■ This is the trick ! ■■■

Trick ^①	Specify a range so that the Anchor Point is in the center of the search area.		
Trick [®]	Specify a range wider than the Anchor Point (About 3 times larger). If the range is too large, the search area will expand and processing speed will decrease.		

process 1 4 : Time and image storage settings		Time
[Standard (sec)] → Allows you to set to operation. *When the standard to bar on the main screen [Limited (sec)] → If the set time is exce be made. [Save image] → The image of the saved. *The frames of checkp JPEG images.	the standard time for that time elapses, the elapsed time a changes to yellow. ceeded, a NG judgment will OK/NG judgment can be oints, etc. can also be saved as	Disable Standard (sec) 30 ‡ Limited (sec) 60 ‡ Save Image OK fail Area External Output OUT0 OUT1
process 1 5 : Flow methods setting		Save Image
Please set up the inspection flow at your choice.		External Output
Sequentiality Check registered checkpoint	s in order.	OUT0 OUT1 OUT2 OUT3 OUT4 OUT5
Batch Check all registered checkpo	ints at once.	Flow
One Shot Check all registered checkpo	ints only once.	Apoly
* [Sequentiality] and [Batch], the mode is to search for OKs up to the maximum time limit set in process 14.		
process 1 6 : Save Settings		Save Image
Click the "Apply" button in the lower right corner to save the settings.		External Output
		OUT0 OUT1 OUT2 OUT3 OUT4 OUT5
		Flow Sequentiality * Apply
process 1 7 : Confirmation of Settings		File Job Settings System S
Return to the main screen, select the Job ID created in Process 7 from		Change Reterence ID
"Change Job ID" in the "File" menu, and confirm the judgment status with		Import/Export Log Out
the Start button.		Reboot Shutdown
		File Job Setängs System Settings View Help
		Start 00:00

Operation procedure (worker mode)

Explanation	Image
process 1 8 : Login	RICOH
Log in with the worker's user ID. *User ID is recorded as data in the operation log.	User ID : Login
process 1 9 : Job ID	Change Job ID
Enter the Job ID from the pulldown.	Input [Job ID].
	Cancel OK
process 2 0 : Reference ID	Change Reference ID
Enter the Reference ID.	Input [Reference ID].
*The entered data will be recorded in the operation log.	
(The data entered will be recorded in the operation log.)	Cancel
*The camera flow starts automatically when the Reference ID is entered.	
* supporting information 	Preset Settings
The Job ID and Reference ID can be omitted in the preset settings.	Job ID Disable blank Job ID Display the Job ID input dialog when the work flow is completed Enter Job ID and Reference ID at the same time Use a fixed Job ID Use the camera code function for input Extraction Start Point Num. of Extracted Char. O Cancel OK